

-
- 15 Bldg#17166
Date Taken: 10/6/2014
Taken By: AJ Morales
Unit#211 was inspected at this location.



- 16 unit#211
Date Taken: 10/6/2014
Taken By: AJ Morales
Bldg#17166 unit#211 was inspected for wind mits.



17 rafter label
Date Taken: 10/6/2014
Taken By: AJ Morales
Bldg#17166 unit#211



18 single wrap
Date Taken: 10/6/2014
Taken By: AJ Morales
Bldg#17166 unit#211



19 single wrap pic#2
Date Taken: 10/6/2014
Taken By: AJ Morales
Bldg#17166 unit#211



20 8d nails
Date Taken: 10/6/2014
Taken By: AJ Morales
Bldg#17166 unit#211



21 nail distance

Date Taken: 10/6/2014

Taken By: AJ Morales

distance between nails were more than 6".

Bldg#17166 unit#211



22 5/8" sheathing

Date Taken: 10/6/2014

Taken By: AJ Morales

Bldg#17166 unit#211

