

---

23 Bldg#17053 (H)

Date Taken: 10/6/2014

Taken By: AJ Morales

Unit#230 was inspected for wind mits  
at this location.



24 unit#230

Date Taken: 10/6/2014

Taken By: AJ Morales

Bldg#17053 (H) unit#230 was  
inspected for wind mits.



---

25 sheathing label  
Date Taken: 10/6/2014  
Taken By: AJ Morales  
5/8" thickness.  
Bldg#17053 (H) unit#230



26 sheathing thickness  
Date Taken: 10/6/2014  
Taken By: AJ Morales  
5/8"  
Bldg#17053 (H) unit#230



---

27 8d nails  
Date Taken: 10/6/2014  
Taken By: AJ Morales  
Bldg#17053 (H) unit#230



28 nail distance  
Date Taken: 10/6/2014  
Taken By: AJ Morales  
8d nails are less than 6" apart.  
Bldg#17053 (H) unit#230





---

29 single wrap  
Date Taken: 10/6/2014  
Taken By: AJ Morales  
Bldg#17053 (H) unit#230



30 single wrap pic#2  
Date Taken: 10/6/2014  
Taken By: AJ Morales  
Bldg#17053 (H) unit#230

