

-
- 1 Bldg#16942
Date Taken: 10/6/2014
Taken By: AJ Morales
Unit#255 was inspected at this
location for wind mits.



- 2 unit#255
Date Taken: 10/6/2014
Taken By: AJ Morales
unit#255 was inspected at bldg#16942
for wind mits.



-
- 3 single wrap
Date Taken: 10/6/2014
Taken By: AJ Morales
Bldg#16942 unit#255



- 4 19/32" sheathing
Date Taken: 10/6/2014
Taken By: AJ Morales
Bldg#16942 unit#255



- 5 8d nails
Date Taken: 10/6/2014
Taken By: AJ Morales
Bldg#16942 unit#255



- 6 nail distance
Date Taken: 10/6/2014
Taken By: AJ Morales
distance between nails were more than
6", but less than 12".
Bldg#16942 unit#255

